


# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

Corner not previously established. This corner established by survey as defined in the 2009 Manual of Surveying Instructions.

Township 3 North, Range 40 East  
X-3



## Subsequent survey:

N/A

## Description of evidence found:

N/A



## Description of monument and accessories established to perpetuate the location of this corner.

At position determined by survey, I set a 2 ins. diam. aluminum cap, on a 5/8 ins. diam. x 30 ins long iron rod, marked as shown. From which:

A ponderosa pine, 20 ins. diam., bears S. 18° E., 24.2 ft. dist., marked "C1/4S31BT".

A chisled "X" bears S. 11° W., 58.6 ft. dist., on NW. face of basalt rock in place.

A ponderosa pine, 6 ins. diam., bears S. 65° W., 79.3 ft. dist., marked "XBT".

A 5/8" x 30" long iron rod with yellow plastic cap marked "BROCKAMP LAND SURVEYING PLS 78556" bears N. 19° W., 9.3 ft. dist.

No available NE bearing object.


Corner position falls in open timber on SE slope.

Bearings are made with a hand compass, magnetic declination = 15°E.

I hereby certify that the above corner point was perpetuated as herein described on 6/17/2018.

Witnessed by:  
Matt Brockamp, LS  
Austin Brockamp

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

  
OREGON  
MAY 20, 2015  
MATTHEW R. BROCKAMP  
78556

Registration expires 12/31/2019

<b>UNION COUNTY SURVEYOR</b>	
Date Received	<u>7/19/18</u>
Date Filed	<u>9/13/18</u>
Filed By	<u>M. J. Gilman</u>
File Number	<u>055-2018R</u>

