USDA-FOREST SERVICE GPO 94 Index File No. J-13 T 3S R. 33½ E Merid. WILLAMETTE	CORNER RECORD (SEARCH) Tract or Cor. SEC. 10 R.D. LA GRANDE County UNION Survey No. No. WALLOWA-WHITMAN State OREGON
CORNER DIAGRAM R336 / 2 R 33½ F	DESCRIBE CORNER MONIMENT FORMS
PHOTO IDENTIFICATION DATA Photo No. Filed At.	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND Sec. 15, T3S, R33½E, 14" western larch snag, is in fair conditistion scribe visible, brs. S. 58° E. 28 lks. Sec. 13, T3S, R33 E, 6" western larch snag down, fair condition scribe visible N. 37° W. Placed location poster on 8" douglas fir, brs. N. 45° E. 10° 4"
Object Ident. Ident. By Signature	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
PLANE COORDINATE POSITION DATA State Zone X Y Estab. By	
Signature DAVE DAHLSTROM	Title Division Headquarters Date 7100-52 (3/68)

UNION	COUNTY		
SURVEYOR			

Date Received____

Date Filed <u>/2 - /8 -87</u>

& G. LANGLITZ DEPUTY

File No. 219-87R