
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original comer establishment:

Corner not previously established.



Description of corner evidence found:

None.



See map of survey dated 4-86.

Description of monument and accessories lestablished to perpetuate the original location of this corner: At the position determined by survey, I set a 2½1x3011 aluminum pipe with aluminum cap marked as shown below, 2811 in the ground with a surrounding ring of stones, from which:

A 5/8"x30" rebar with a plastic cap marked BGA Survey Marker, bears N  $51^{\circ}$  E

A 5/8"x30" rebar with a plastic cap marked BGA Survey Marker, bears N  $54^{\circ}$  W,

Set a steel fence post approximately 5 feet North with a 54-2 and a 54-9 sign attached.


Set a steel fence post approximately 5 feet East with a 54-2 sign attached.

Corner set 4-17-86 Witness: Greg Blackman

REGISTERED

PROFESSIONAL

AND SURVEYOR



OREGON JULY 10, 1984 DUANE I. GRIFFITH 644\_\_\_\_\_ Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of	County of
State of, I hereby certif	ly that the within instrument was filed in this office
for record on the day of	
(COUNTY OFFICIAL)	
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE -1983-793-276