


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established by Rufus S. Moore under General Land Office contract number 451, dated June 12, 1882. Surveyor General record state:

Set pine post 3 feet long 3 ins square 18" in the ground for 1/4 sec cor marked 1/4 on W face from which:

A tamarack 10" diameter bears N26°E 10 lks dist marked 1/4 BT
A fir 8" diameter bears S19°W 15 lks dist marked 1/4 BT



No record of subsequent remonumentation found in county records.

Description of corner evidence found:

Found 10" tamarack, rotted, dead and down, with scribes visible
Found root hole at record position for Southwest BT

UNION COUNTY SURVEYOR

Date Received 4-30-86
Date Filed 5-1-86
By G. LANGLITZ, DEPUTY
File No. 20-86 R

See map of survey dated 4-86.

Description of monument and accessories established to perpetuate the original location of this corner: At record bearing and distance from the original BT, I set a 2 1/2'x30" aluminum pipe with aluminum cap marked as shown 29 inches in the ground from which:


New BTs

A 12 inch diameter White Fir bears N23°E 19.72 feet marked 1/4 S23 BT
A 13 inch diameter White Fir bears N74°W 19.49 feet marked 1/4 S22 BT

Set steel fenceposts approximately 5 feet West with 54-2 sign and approximately 5 feet East with 54-2 and 54-4 signs attached

Corner set April 15, 1986

Witness: Rick Robinson



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

Brass washer marked OPLS 644 nailed to Bt blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by

(COUNTY OFFICIAL)

(DEPUTY)