
CERTIFIED RECORD OF LAND CORNER MUNICIPALITY


History of original corner establishment:

Corner not previously established.



Description of corner evidence found:

None.



See map of survey dated 4-86.

Description of monument and accessories lestablished to perpetuate the original location of this corner: At position determined by survey, I set a 2½ x30" aluminum pipe with aluminum cap marked as shown below, 30" in the ground from which:

A 12" diameter White Fir bears S 46° E, 11.57 feet, marked C4 S23 BT.


A 12" diameter Douglas Fir bears \$ 44° W, 35.25 feet, marked X BT.

Set a steel fence post approximately 5 feet North with a 54-2 and 54-9 sign attached.

Set a steel fence post approximately 5 feet West with a 54-2 sign attacked.

Corner set: 4-18-86

Witness: Greg Blackman, Rick Robinson



OREGON
JULY 10, 1964
DUANE I. GRIFFITH

REGISTERED

PROFESSIONAL AND SURVEYOR

Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of	County of
	y certify that the within instrument was filed in this office
for record on the day of	, 19
	by
	(DEPUTY)

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276