


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

P-21

History of original corner establishment:

Corner established by General Land Office contract survey  
The original notes state;  
At 40.00 ch a pine post 3 ft long 3 in. sq., 18" in ground  
for  $\frac{1}{4}$  corner from which;  
A pine 12" in dia bears N10°W 125 lks dist marked  $\frac{1}{4}$ SBT;  
A pine 10" dia bears N46°E 48 lks dist marked  $\frac{1}{4}$ SBT;



Description of corner evidence found:


found stone marked  $\frac{1}{4}$   
In section 24 found 14" pine at correct bearing and distance . No scribe;

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 30" galvanized pipe with eight inch plate welded to bottom and a bronze cap on top. The hole was back filled with stone and tamped soil and raised stone monument.

I stamped the disk

From the monument the original bearing trees were;  
Pine 14" in diam at correct bearing and distance. I established the following new bearing trees;  
Reset the 14" pine at N46°E at a distance of 32.6 ft and scribed  $\frac{1}{4}$ SBT;  
Yellow pine 12" in dia bears S16°W at a distance of 134 ft. and scribed  $\frac{1}{4}$ SBT;  
The distance measured to center of respective trees on level.  
I placed bearing tree signs on both old and new bearing trees and painted stripe around trees. I placed a steel fence post with USFS sign 54-4 attached near the corner.



Office of.....County surveyor..... County of..... Union.....  
State of.....OREG....., I hereby certify that the within instrument was filed in this office  
for record on the 23 day of July, 1970, at 3 o'clock P.M., (signed)  
County surveyor by [Signature] (DEPUTY)  
(COUNTY OFFICIAL)

ION COUNTY SURVEYOR

Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 365-84 R