CERTIFIED RECORD OF LAND CORNER MONUMENTATION

	W-23
History of original corner establishment:	DIAGRAM
Corner established by General Land Office contract survey.	T3S R33\(\frac{1}{2}\) EWM
The original notes state; Ran west between sections 24 and 25. 39.94 ch. set basalt stone 19x18x8", 7" in ground for ‡ corner marked ‡ on north face from which; Pine 20" in dis bears N19°E 8 1ks dist marked ‡9BT;	<u>924</u> 525
Pine 10" in dis bears S8°E 23 1ks dist marked #SBT;	

Description of corner evidence found:

Found stone marked \(\frac{1}{6}\)
In section 25 found 24" down log.

Description of manument and accessories I established to perpetuate the original location of this corner

with an eight inch plate welded to bottom and a bronse cap	☆ COR
on top. The hole was back filled with stone and tamped soil.	T3S R331
I stamped the disk	<u>524</u> 525
From the monument the original bearing trees are (none); I established the following new bearing trees;	ORE LIC 381
A red fir 7" dia bears N45°W at a distance of 11.1 ft and scribed \$SBT:	1970
A longe pale pine 8" in dia bears S64°E at a distance of 13.2 ft soribed \$SBT;	and .
The distance measured to center of respective trees on level. I placed bearing tree signs on both old and new bearing trees an painted stripe around trees. I place a steel fence post with USF attacked near the corner.	d 3 sign 54-4

Office of County survey	County of Union	UPMON COUNTY SURVEYOR
for record on thetdoy ofJuly County surveyor (COUNTY OFFICIAL)	ertify that the within instrument was filed in th	l late Kecaivad
	, marketi 0	By