CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1882, under GLO Contract 451, Rufus S. Moore set a stone 12x8x6, from which a 10" Tamarack bears N70°W, 8 lks. and a 6" Fir bears East, 3 lks. Index File No. T-21 DIAGRAM T3S R33 1/2E 26+25

Description of corner evidence found:

Found BLM 3 1/4" brass cap on 2 1/2" iron pipe rising 8", stamped:

Bearing trees found:
A 10" W. Larch bears N70°W, 8 lks. to root hole, dead and down.

T3S R33 1/2E 1/4 S26+S25 1975

A 15" D. Fir bears N23°W, 2.8 ft., scribing visible "1/4 S26 BT".

A 13 1/2" W. Larch bears N83 1/2°E, 32.7 ft.,

scribing visible "1/4 S25 BT".
A 12" Fir, dead & down, broken off stump, with healed blaze.

Description of monument and accessories I established to perpetuate the original location of this corner:

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Set metal fence post 4 ft. north of corner.

From 2115, follow 2115-108 southwesterly 1.5 mi. to the summit. the right you will find a tree marked with a yellow tag. Corner is 120 ft. east.

UNION COUNTY **SURVEYOR** Date Received 7-2-84 Date Filed 7-3-84 BY G. LANGETTZ DEPUTY

File No. 895-84 R

Compass Declination: 19 1/2°E Witness: J. Sutton

I hereby certify the above described corner monument and/or accessories was established as described on May 29, 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR	
Hullon	
OREGON JULY 13, 1979 B. A. SUTTON 1 8 4 8	

Office of	County of
State of, I hereby certify for record on the day of	that the within instrument was filed in this office
(COUNTY OFFICIAL)	y(DEPUTY)

Remonumentation of Certain Original Corner Points, T. 3 S., R. $33\frac{1}{2}$ E., Willamette Meridian, Oregon

CHAINS

The cor. of secs. 7, 12, 13, and 18, determined at record bearing and distance from the remains of the original bearing trees:

- A root hole, bears N. 35° E., 26 lks. dist., with a down and decayed western larch alongside, 12 ins. diam., with scribe marks BT visible on decayed blaze.
- A decayed western larch snag, 24 ins. diam., bears S. 42° E., 16 lks. dist., with soribe marks S R34E S18 visible on decayed blaze.
- A pine snag, 9 ins. diam., bears N. 19° W., 42 lks. dist., with scribe marks T3S R33½E S12 BT risible on partially healed blaze.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground with brass cap mkd.

T 3 S R 33 E R 34 E S 12 S 7 13 S 18 1975

from which new bearing rees

- A fir, 17 ins. diam., bears N. 35½° E., 57 lks. dist., mkd. T3S R34E S7 BT.
- A western/larch, 18 ins. diam., bears S. 424° E., 63 lks/ dist., mkd. T3S 834E S18 BT.
- A fir, 12 ins. diam., bears 3, $55\frac{1}{2}^{\circ}$ W., $35\frac{1}{2}$ lks. dis., mkd. T3S R33½E S13 BT
- A fir, 10 ins. diam., bears N. 134° W., 18 lks. dist., mkd. T3S R33½E S12 BT.

Subdivision, T. 3 S., R. 33½ E., Willamette Meridian, Oregon

(Remonumenting corners established by Rufus S. Moore, Deputy Surveyor, in 1882)

The $\frac{1}{4}$ sec. cor. of secs. 25 and 26, monumented with a baselt stone, 12 x 8 x 6 ins., loosely set 2 ins. in the ground, no marks visible, from which the remains of the original bearing trees:

- A fir snag, 12 ins. diam., bears East, 3 lks. dist., with healed blaze.
- A western larch snag, 7 ins. diam., bears N. 70° W., 8 lks. dist., with scribe marks \ S visible on open blaze.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

UNION COUNTY SURVEYOR

Date Received 3/5/15

Data Filad (3

BY CHIS L-DEATY

File No. 372-2013R

Remonumentation of Certain Original Corner Points,

T. 3 S., R. 33½ E., Willamette Meridian, Oregon AINS T 3 S R 33½ E \$ 26 | \$ 25 1975 from which new bearing trees A western larch, 12 ins. diam., bears N. 80½° E., 50 1ks. dist., mkd. 1/4 S25 BT. A fir, 14 ins. diam., bears N. 25° W., 4 lks. dist., mkd. 4 S26 BT. Deposit corner stone alongside iron post. The cor. of secs. 23, 24, 25, and 26, monumented with a basalt stone, $18 \times 18 \times 12$ ins., firmly set 6 ins. in the ground, no marks visible, from which the remains of the original bearing trees: A Mr snag, 28 ins. diam., bears S. 88° 1., 181 s. dist., with scribe marks BT visible on partially healed blaze. A root hole, bears N. 55° W., 40 116. dist., with a down and decayed pine alongside, 36 ins. diam., with scribe marks T3S R33½E S22 BT visible on decayet blaze. At the corner point Set an iron post, 28 ins. long, $2^{1}\!\!\!/_{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd. T 3 S R 33½ E 23 S 24 26 S 25 1975 **UNION COUNTY** SURVEYOR from which new bearing trees A fir, 6 ins. diam., bears N. 61° E., 24 lks. dist., mkg. T3S R33½ 824 BT. Date Received A fir, 8 %hs. diam., bear S. 80° E., 212 lks. dist., wkd. T3S R33½E S21 BT. A fir, 17 ins. diam., bears \$. 66° W., 47 lks. dis., mkd. T3S R33½E S26 B. A f**y**r, 15 ins. diam., bears N. 5½° W., 41 lks. #ist., mkd. T3S R33½E S23 BT. Deposit corner stone alongside iron post. The cor. of secs. 26, 27, 34, and 35, monumented with a basalt stone, 18 x 12 x 8 ins. (record, 20 x 13 x 10 ins.) firmly set 10 ins. in the ground, no marks visible, from mich the remains of the original bearing trees A sawed pine stump, 30 ins. diam., bears N. 82° E.,

27 lks. dist., no marks visible.

Date Filed

File No.