


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. V-19

History of original corner establishment:

In 1882, under GLO Contract 451, Rufus S. Moore set a stone 12x12x10, from which a 4" Pine bears N10°W, 40 lks. and a 6" Pine bears S13°E, 25 lks.



Description of corner evidence found:

Found original stone 12x12x10 with "1/4" marked on it.

Found a 24" P. Pine stump bearing S13°E, 16.5 ft., no marks.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2 1/2"x30" aluminum capped aluminum pipe rising 6", stamped:

New BT's:

- A 6" W. Larch bears N2°W, 94.2 ft., scribed 1/4 S26 BT.
- A 9" W. Larch bears S50 1/2°W, 45.5 ft., scribed 1/4 S35 BT.

T3S R33 1/2E
 S26
 1/4 ———
 S35
 1984
 RLS 1848

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Set metal fence post 4 ft. north of corner.

Declination: 19 1/2°E
Witness: G. Arrand

From 2115-108, take 2115-075 southwesterly 2 mi. Road hooks around in a draw, goes west, and when it turns and goes south go 300 ft. The corner is down the hill to the west 250 ft.

I hereby certify the above described corner monument and/or accessories was established as described, on June 5, 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>B. A. Sutton</i>
OREGON JULY 13, 1979 B. A. SUTTON 1848

Office of..... County of.....

State of..... I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Received <u>7-2-84</u>
Date Filed <u>7-3-84</u> <small>PRO-798-276</small>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>899-84 R</u>