


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. V-21

History of original corner establishment:

In 1882, under GLO Contract No. 451, Rufus S. Moore set a post, from which a 10" Pine bears S24°W, 20 lks.; a 10" Pine bears N80°W, 30 lks.; a 10" Pine bears N78°E, 85 lks.; and a 12" Pine bears S78°E, 18 lks.



Description of corner evidence found:


Bearing Trees Found:

- A 25" P. Pine bearing N50°E, 30.2 ft., scribed "S25"
- A 30" P. Pine bearing W35°E, 42.2 ft., scribed "BT", stump rotted.
- A 28" W. Fir bearing S50.5°W, 41.5 ft., scribed "1/2E S35".
- A 24" P. Pine bearing N55°W, 79.6 ft., scribed "1/2E S2".

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2 1/2"x30" aluminum capped aluminum pipe, rising 14" in mound, New BT's: stamped:

- An 8" P. Pine bearing N21 3/4°W, 15.9 ft., scribed T3S R33 1/2E S26 BT.
- A 9.5" W. Fir bears N45°E, 37.9 ft., scribed T3S R33 1/2E S25 BT.
- A 10" W. Fir bears S73 1/4°E, 10.0 ft., scribed T3S R33 1/2E S36 BT.
- A 6.5" P. Pine bears S58 3/4°W, 22.0 ft., scribed T3S R33 1/2E S35 BT.



Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March, 1982. Set metal fence post 4 ft. south of corner.

Compass Declination: 19 1/2°E

Witness: J. Sutton

From 2115, follow 2115-108 up the hill southwesterly 2 mi. Tree on right with yellow tag. Corner is 150 ft. west of road.

I hereby certify the above described corner monument and/or accessories was established as described, on May 29, 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 13, 1979
B. A. SUTTON
1848

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received 7-2-84
☆ GPO-798-276
Date Filed 7-3-84
By G. LANGUITZ DEPUTY
File No. 900-84R