CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishments

Corner established by General Land Office contract survey
The original notes state:
Runs West between sections 25 and 36.
40.00 Set pine post 3! long, 3" square 18" in ground for \$\frac{1}{2}\$ section corner marked \$\frac{1}{2}\$ Section on the West face from which:
Pine 4" dia bears N57"W 7 lks dist marked \$\frac{1}{2}\$ SBT
Pine 20" dia bears \$\$40°E 28 lks dist marked \$\frac{1}{2}\$ SBT.

Description of corner evidence found:

In section 36, found 24" down fir log with scribe.

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 30" galvanised pipe with an eight inch plate welded to bottom and a bronze cap on top. The hole was back filled with stone and tamped soil.

I stamped the disk.

From the monument the original bearing trees were; (none). I established the following new bearing trees; Red Fir 14" dia N70°W at a distance of 29 ft. and

scribed \$18 32 die 514 W at a distance of 34.5 ft. and

The distance measured to center of respective trees on level. I placed bearing tree signs on both old and new bearing trees and painted stripe around trees. I placed a steel fence post with USFS sign 54-4 attached near the corner and indicating USFS land to the north and private land to the south. with USFS sign 54-2 attached to steel post.

	T 3S	R33½E	
	S	25	
	S	36	
\	ORE 1	LIC 381 970	

l cor

for record on the 4th county Surv	oy or	rify that the	within inst	rument was file	d in this SHEON COUNTY P. 1 pm, (algnoral RVEYOR
(COUNTY OF	TICIAL)			Ser Control of the Co	Date Received
			<i>:</i>		Date Filed
•					Ву
26.7100.57 (0/66)				,	F'e No. 367-84 R

Form R6-7100-57 (9/66)

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1882, under GLO Contract 451, Rufus S. Moore set a post, from which a 4" Pine bears N57°W, 7 lks. and a 20" Fir bears S40°E, 28 lks.

Index File No. V-23 DIAGRAM T3S R33 1/2E 25 1/4-36

Description of corner evidence found:

Found 3" brass cap on 2 1/2" iron pipe rising 24" in mound, stamped:

Found metal fence post S30°E, 4 ft. w/ attn. sign.

Bearing trees found:
A 26" Fir stump bears \$40°E, 19.0 ft.,
scribing visible "1/4 S BT", dead & down.
A 15" dead standing D. Fir bears \$8°E,

33.9 ft., scribing visible "1/4 S BT". A 17.5" D. Fir bears N69°W, 28.5 ft.,

blaze healed.

1/4 COR T3S R33 1/2E

S25 S36

ORE LIC 381 1970

Description of monument and accessories I established to perpetuate the original location of this corner:

New BT:

A 15" W. Fir bears S47°W, 40.2 ft., scribed 1/4 S36 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Set metal fence post 4 ft. west of corner.

Declination: 19 1/2°E Witness: D. Scott

From 2115, follow 2115-108 southwesterly up the hill 2 mi. to posted line. Follow posted line east 1/2 mi. to corner.

I hereby certify the above described corner monument and/or accessories was established as described, on June 5, 1984.

UNION COUNTY SURVEYOR	
Date Received 7-2-84 Date Filed 7-3-84 By G.LANGLITE DEPUTY File No. 901-84 R	REGISTERE PROFESSION LAND SURVE OREGON JULY 13. 1970 B. A. SUTTO 1 8 4 8

Office of	County of
State of / hereby cert	ify that the within instrument was filed in this office
for record on the day of	, 19
	. by
(COUNTY OFFICIAL)	(DEPUTY)

YOR