CERTIFIED RECORD OF LAND CORNER MONUMENTATION

distory of original corner establishment.	
distory of original corner establishment: The exterior lines of Township 3 South, Range 33 East were originally established by Rufus L. Moore under Contract No. 451 dated June 12, 1882.	DIAGRAM TAS
Page 14 of the original notes state that at the corner a 313" square	5

post was set 24" in the ground from which: A 8" pine bears N74°W 53 LKs (35.0 ft) marked $\frac{1}{4}$ S BT.

A 7" pine bears S39°W 43 LKs (28.4 ft) marked $\frac{1}{4}$ S BT.

Note: Township 2S, Range 33E was later surveyed, resulting in the section configuration shown.

A-23	
DIAGRAM TAS R33E S34	
1/4 SI T3S R33E	

No record of subsequent re-monumentation found in County records. Description of corner evidence found:

No evidence of original monument was found. No BT's found.

Corner was re-established by survey

Description of manument and accessories I established to perpetuate the original location of this corner:

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 18 inches in ground to hard pan and surrounded with a mound of stones to the top.

Set steel fence post on Township line E of corner and attached signs 54–2 and 54–4 and 54–9. Established 2 new BT's: A 9½" fir bears S47°E 33.2 ft, scribed \$\frac{1}{4}\$S1 BT.

A 10" fir bears $S20\frac{1}{2}$ °W 49.1 ft scribed $\frac{1}{4}$ S1 BT.

New BT's have a lower blaze scribed BT with brass washer stamped PLS 1106 nailed flush. Attached signs 54-3 and 54-4 and painted red ring around all BT's.

PROFESSIONAL LAND SURVEYOR	TAS R33E
TANKE OOK VET CK	S34 \
Willia R. Wells	1/4 51
OREGON JULY 22, 1977 WILLIAM R. WELLS 1106	T35 R33E 1979 PLS 1106
uy ut. Union	
	OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

(DEPUTY)

(COUNTY OFFICIAL) Form R6-7100-57 (9/71)

SURVEYOR Date Received

WHION COUNTY