


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. T-21

History of original corner establishment:

In 1882, under GLO Contract No. 451, Rufus S. Moore set a post, from which a 6" Pine bears N35°W, 17 lks. and a 6" Pine bears S89°E, 10 lks.



Description of corner evidence found:

No corner evidence found.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2 1/2"x30" aluminum capped aluminum pipe rising 5", stamped:

Set 2 reference monuments: 5/8" iron rods with aluminum caps 1.5" diam., one bearing due east and one due west, stamped:

T3S R33E
1/4
S26 S25
1984
RLS 1848

RM	RM	Reference monuments are
S 26	S 25	each 15.0 ft. from
RLS 1848	RLS 1848	corner.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Set metal fence post 4 ft. north of corner.

Declination: 19 1/2°E

Witness: D. Scott

From 2110-220, NE'ly on 2115-125 1/2 mi. North 800 ft. to corner. Corner is in clear-cut southwest from a fringe of standing lodgepole.

I hereby certify the above described corner monument and/or accessories was established as described on November 18, 1983.

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
JULY 13, 1979
B. A. SUTTON
1848

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 7-2-84
Date Filed GPO-7-3-84
By G. LANGLITZ, DEPUTY
File No. 873-84 R