


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1882, under GLO Contract No. 451, Rufus S. Moore set a post, from which a 15" Pine bears N42°W, 22 lks.; an 18" Pine bears N40°E, 30 lks.; a 15" Pine bears S70°E, 26 lks.; and a 15" Pine bears S38°W, 52 lks.

Index File No. V-21



Description of corner evidence found:

No corner evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2 1/2"x30" aluminum capped aluminum pipe rising 5", stamped:

Set 4 reference monuments: 5/8"x30" iron rods with aluminum caps at 45° in each quadrant.

Caps marked: 15.0 ft. from corner.

RM
SEC No.
RLS 1848

T3S R33E
S26 | S25
S35 | S36
1984
RLS 1848

Painted monuments and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Set metal fence post 4 ft. north of corner.

Declination: 19 1/2 °E

Witness: N. Petz

From the intersection of 2110-320 and 2110-256, go east 300 ft. to 1/4 corner between S35 & S36. Follow posted line 1/2 mi. north to corner.

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>B. A. Sutton</i>
OREGON JULY 13, 1979 B. A. SUTTON 1848

I hereby certify the above described corner monument and/or accessories was established as described on October 22, 1983.

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR
Date Received <u>7-2-84</u>
Date Filed <u>7-3-84</u>
By <u>G. LANGLITZ DEPUTY</u>
File No. <u>876-84R</u>