


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. ^A ~~16~~

History of original corner establishment:

None.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" X 30" galvanized pipe and brass cap marked: Set pipe 12" in the ground and mound of stone around to cap. From which by magnetic declination of N20°E: A 16" pine bears N36°E, 80.8 ft. scribed E1/16S34 BT. A 40" pine bears S47°E, 92.9 ft. scribed E1/16 S3 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-9s and brass washers stamped PLS 1051 on BTs. Placed 54-2 and 54-9 on steel fence post 5' north and 54-2 on steel fence post 5' west of the corner.

T2S R34E
 S34
 E —+— 1/16
 S3
 T3S
 OR PLS 1051
 1980

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland
Ron Gilroy

November 4, 1980

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Barry B. Barbour

OREGON
 OCT. 17, 1975
 BARRY B. BARBOUR
 1051

Office of...County...Surveyor..... County of...Union.....
 State of...Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the 30th day of...January....., 19...81
 by
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____
 Date Filed GPO-798-278
 By _____
 File No. 370-84R