


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File no. C-21

History of original corner establishment:

Corner was originally established by Rufus S. Moore under GLO contract No. 451, during November, 1882. Surveyor General's notes state: "Set a post 3 ft. long, 3 ins. square., 24" in the ground for 1/4 sec, cor. marked 1/4S on W face. From which: A pine 7 ins. diam. bears S47°W, 74 lks. dist. marked 1/4S BT. A pine 15 ins. diam. bears S25°E, 69 lks. dist. marked 1/4S BT."




Description of corner evidence found:

Found no trace of record post. Found 26" pipe with grown over blaze bearing S25°E, 45.5 ft. Opened tree and found 1/4S scribed. A 20" pine bears S48°W, 47.5 ft. with grown over blaze.

Description of monument and accessories established to perpetuate the original location of this corner:

At the above point set 2 1/2" X 30" galvanized pipe and brass cap marked: Set pipe 8" in the ground and mound of stone around to cap.

From which by magnetic declination on N20°E:
A 12" fir bears S35°E, 95.3 ft. scribed 1/4S1 BT. Painted blazes red and 6" red band around. Placed 54-3, 54-4 and brass washers stamped PLS 1051 on BTs. Placed 54-3s and 54-4s on old BTs. Placed 54-4 on steel fence post 5' south of the corner.



I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland
Harlan Eden

September 23, 1980

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of...County...Surveyor..... County of...Union.....

State of...Oregon....., I hereby certify that the within instrument was filed in this office

for record on the...30th day of...January....., 1981.

..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**
Date Received _____
Date Filed _____
By _____
File No. 374-84 R