

Index File No. E-5

CORNER RECORD (SEARCH)

Tract or Survey No. _____ Cor. No. _____


T 35 R. 34 E

R.D. LaGrande County Union

Merid. Willamette

N.F. W-W State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Sec. 5 - 36" D.F. stamp Fair condition Bottom of
Blaze remains
Sec. 6 - 30" P.P. stamp poor condition scribe visible
Sec. 7 - 12" D.F. stamp down poor condition scribe grown over
Sec. 8 - 24" P.P. Live Good condition scribe grown over

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature David L. Dahlstrom C.E.T. Title _____ Division _____ Headquarters LaGrande Date 9-11-78

7100-52 REV. 65 5

UNION COUNTY SURVEYOR

Date Received _____

Date Filed 12-18-87

By G. LANGLITZ, DEPUTY

File No. 226-87R

E-5