


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-23

History of original corner establishment:

Corner was originally established by Rufus S. Moore under GLO contract No. 451 during November, 1882. Surveyor General's notes state: "Set a basalt stone 18x15 ins., 12 ins. in ground for 1/4 sec. cor. marked 1/4 on W face. and raised mound of stone alongside. Pits impracticable. No trees in limits.



Description of corner evidence found:

Found no trace of record stone or mound.

Corner falls on open west slope about 500' west of track road.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2"x30" galvanized pipe and brass cap marked: Set pipe 24" in the ground and mound of stone around to cap.

From which by magnetic declination of N20°E: A 28" pine bears S10°W, 72.8 ft. scribed 1/4S12 BT. A 10" pine bears N14°W, 89.0 ft. scribed 1/4S1 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-4s and brass washers stamped PLS 1051 on BTs. Placed 54-4 on steel fence post 5' east of the corner.

T3S R34E
S1
1/4 —+—
S12
OR PLS 1051
1980

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland
Harlan Eden

October 10, 1980

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of..... County Surveyor..... County of..... Union

State of..... Oregon....., I hereby certify that the within instrument was filed in this office for record on the...30th day of..... January....., 1981.

..... by (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received _____
Date Filed _____
By _____
File No. 378-84 R