


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-24

History of original corner establishment:

None.



Description of corner evidence found:

None.

Corner falls west of old logging road.

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" X 30" galvanized pipe and brass cap marked: Set pipe 25" in the ground and mound of stone around to cap.

From which by magnetic declination of N20°E;

A 12" fir bears N61°E, 56.3 ft. scribed E1/16S1 BT.

A 24" pine bears S80°E, 58.1 ft. scribed E1/16S12 BT.

Painted blazes red and 6" red band around. Placed 54-3s, 54-9s and brass washers stamped PLS 1051 on BTs. Placed 54-2 and 54-9 on steel fence post 5' east and 54-2 on steel fence post 5' south of the corner.

T3S R34E
S1

E —+— 1/16

S12

OR PLS 1051
1980

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland
Doug Moser

October 20, 1980

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of...County...Surveyor..... County of Union.....

State of...Oregon....., I hereby certify that the within instrument was filed in this office for record on the 30th day of January....., 1981.

..... by (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR	
Date Received	_____
Date Filed	_____
By	_____
File No.	379-84R