


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Index File No. F-23

None.




Description of corner evidence found:

None.

Corner falls about 50' east of track road near the end of road.

Description of monument and accessories I established to perpetuate the original location of this corner:



At surveyed point set 2 1/2" X 30' galvanized pipe and brass cap marked; Set 22" in the ground and mound of stone around to cap.

From which by magnetic declination of N20°E:

An 18" pine bears N22°E, 30.2 ft. scribed CN1/16S12 BT. A 13" pine bears S49°E, 48.0 ft. scribed CN1/16S12 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-9s and brass washers stamped PLS 1051 on BTs. Placed 54-2 and 54-9 on steel fence post 5' east and 54-2 on steel fence post 5' south of the corner.

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland
Harlan Eden

October 13, 1980

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of.....County Surveyor..... County of..... Union
Oregon
State of....., I hereby certify that the within instrument was filed in this office
for record on the 30th. day of January....., 1981

..... by
(COUNTY OFFICIAL) (DEPUTY)

| | |
|----------------------------------|-----------------|
| UNION COUNTY SURVEYOR | |
| Date Received | _____ |
| Date Filed | _____ |
| By | _____ |
| File No. | 381-84 R |