


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

History of original corner establishment:

None.

Index File No. G-24



Description of corner evidence found:

None.

Corner falls on top of rock bluff 75' south of small fork of McCoy creek.

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" X 30" galvanized pipe and brass cap marked: Set pipe 22" in the ground and mound of stone around to cap. Set pipe tilted left due to rock edge.

From which by magnetic declination of N20°E:

A 10" tamarac bears S59°E, 56.6 ft. scribed CE1/16 S12 BT. A 22" fir bears S56°W, 23.2 ft scribed CE1/16S12 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-9s and brass washers stamped PLS 1051 on BTs. Placed 54-2 and 54-9 on steel fence post 5' south and 54-2 on steel fence post 5' west to soil.

T3S R34E E1/16		
C	—+—	C
S12		
OR PLS 1051		
1980		

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland  
Doug Moser

October 17, 1980

<b>REGISTERED PROFESSIONAL LAND SURVEYOR</b>
--

*Barry B. Barbour*

OREGON OCT. 17, 1975 <b>BARRY B. BARBOUR</b> 1051
--

Office of.....County Surveyor..... County of...Union.....

State of...Oregon..... I hereby certify that the within instrument was filed in this office

for record on the...30th day of...January....., 1981.

..... by .....

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

<b>UNION COUNTY SURVEYOR</b>	
Date Received _____	☆ GPO—798-276
Date Filed _____	
By _____	
File No. <u>385-84R</u>	