


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. J-23

History of original corner establishment:

Corner was originally established by Rufus S. Moore under GLO contract No. 451 during November, 1882. Surveyor General's notes state: "Set apost 3 ft. long, 3 ins. sq., 24 ins. in ground for 1/4 sec. cor. marked 1/4S on N face. From which: A fir 34 ins. diam. bears N25°W, 2 lks. dist. marked 1/4S BT. A fir 11 ins. diam. bears S45°E, 16 lks. dist. marked 1/4S BT."




Description of corner evidence found:

After diligent search found no trace of corner post or BTs. Old rotten fir stump 15' E but no trace of S BT to confirm. Corner falls in east-west fence on top of small ridge.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" X 30" galvanized pipe and brass cap marked: Set pipe 24" in the ground and mound of stone around to cap. From which by magnetic declination of N20°E: An 8" tamarac bears N26°E, 61.9 ft. scribed 1/4S12 BT. A 12" tamarac bears S17°W, 70.0 ft. scribed 1/4S13 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-4s and brass washers stamped PLS 1051 on BTs. Placed 54-2 and 54-4 on steel fence post 5' north and 54-2 on steel fence post 5' west of the corner.



I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland
Harlan Eden

October 13, 1980

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour
**OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051**

Office of... County Surveyor..... County of... Union
State of... Oregon..... I hereby certify that the within instrument was filed in this office
for record on the 30th day of... January....., 19.81
..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**
Date Received _____
Date Filed _____
By _____
File No. 390-84B