


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. L-21

History of original corner establishment:

Corner was originally established by Rufus S. Moore under GLO contract No. 451 during November, 1882. Surveyor General's notes state: "Set a basalt stone 16x10x8ins., 11 ins. in ground for 1/4 secs cor. 70 ft. above dry ravine. marked 1/4 on W face. From which: A pine 12 ins. diam. bears S82°E, 88 lks. dist. marked 1/4S BT. A pine 20 ins. diam. bears N63°W, 157 lks. dist. marked 1/4S BT."




Description of corner evidence found:

Found no trace of record stone. Found small mound of stone from which an 18" rotten pine stump bears S80°E, 125.0 ft. A down and rotten 24" pine, stump hole, bears N63°W, 103.2 ft.

Corner falls about 10' east of N-S fence.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the above point set 2 1/2" X 30" galvanized pipe and brass cap marked: Set pipe 12" in the ground and mound of stone around to cap. From which by magnetic declination of N20°E; A 14" pine bears N39°E, 76.1 ft. scribed 1/4S13 BT. A 15" pine bears N66°W, 139.6 ft. scribed 1/4S14 BT. Placed 54-3s on old BTs. Painted blazes red and 6" red band around. Placed 54-3s, 54-4s and brass washers stamped PLS 1051 on BTs. Placed 54-2 and 54-4 on steel fence post 5' north of the corner.



I hereby certify that the above corner monument was reestablished as herein described.

Witness: Daniel Rowland

October 16, 1980

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of County Surveyor County of Union
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 30th day of January , 1981

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR	
Date Received _____	<small>REG-788-276</small>
Date Filed _____	
By _____	
File No. <u>391-84 R</u>	