


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Index File No. V-25¹


In 1882, under GLO Contract No. 451, Rufus S. Moore set a stone 15x10x10, from which a 10" Fir bears N69°W, 8 lks.; a 10" Fir bears N66°E, 2 lks.; an 18" Fir bears S28°E, 42 lks.; and a 10" Pine bears S48°W, 18 lks.



Description of corner evidence found:

Found BLM 3 1/4" Brass Cap on 2 1/2" Iron Pipe leaning badly to the east--apparent logging damage--stamped:

Bearing Trees Found:



A 23.5" D. Fir bears N25°E, 21.7 ft., (BLM-N23°E, 21 lks) scribing visible "T3S R34E S30 BT"

Original S30 BT, dead and down, scribing visible "T3S R34E S30"

A 22" D Fir bears S26°E (BLM-S28°), 27.7 ft., blaze healed.

An 11.4" D. Fir bears S48°E, 11.9 ft., blaze healed.

An 8.1" D. Fir, original BT., BLM record N69°W, 8 lks.

A 22.2" D. Fir, bears N20°W, 77.9 ft., scribing visible "T3S R33 1/2E S25 BT"

Description of monument and accessories established to perpetuate the original location of this corner:

Reset BLM monument according to measurements shown in BLM 1975 notes and found evidence, cap rising 7" above ground.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March, 1982. Set metal fence post south of corner.

Compass Declination: 19 1/2°E
Witness: N. Petz

From 21, southwesterly on 2100-110 .2 mi. to where road turns south. Corner is west down the hill 250 ft.

I hereby certify the above described corner monument and/or accessories was established as described on September 15, 1983.

UNION COUNTY SURVEYOR
Date Received <u>7-2-84</u>
Date Filed <u>7-3-84</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>902-84R</u>

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>[Signature]</i>
OREGON JULY 13, 1979 B. A. SUTTON 1848

Office of..... County of.....
State of..... I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

T3S34V01

T. 3 S., R. 33½ E., Willamette Meridian, Oregon

CHAINS

The following field notes describe the remonumentation of certain original corner points, township 3 south, range 33½ east, Willamette Meridian, Oregon, as provided for in the General Special Instructions, Group Number 350, Oregon, dated May 3, 1957, "Investigation of Collateral or Physical Evidence of Corner Positions and Accessories Followed by Remonumentation of Corner Points, with New Accessories when Needed."

The remonumentation of original corner points was made at the request of the United States Forest Service, in conjunction with their Land Line Location Program.

The mean magnetic declination is 20° E.

East Boundary, T. 3 S., R. 33½ E.,
Willamette Meridian, Oregon

(Remonumenting corners established by
Rufus S. Moore, Deputy Surveyor, in 1882)

The cor. of secs. 25, 30, 31, and 36, monumented with a basalt stone, 15 x 10 x 10 ins., loosely set 3 ins. in the ground, no marks visible, from which the remains of the original bearing trees:

A root hole, bears N. 66° E., 2 lks. dist., with a down and decayed pine alongside, 10 ins. diam., with scribe marks T3S R34E S30 visible on open decayed blaze.

A fir, 22 ins. diam., bears S. 28° E., 42 lks. dist., with healed blaze.

A fir, 12 ins. diam., bears S. 48° W., 18 lks. dist., with illegible scribe marks visible on partially healed blaze. (Record, pine)

A fir, 8 ins. diam., bears N. 69° W., 8 lks. dist., with scribe marks T3S R33½E S25 BT visible on open decayed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 3 S	
R 33½ E	R 34 E
S 25	S 30
S 36	S 31
1975	

from which new bearing trees

A fir, 24 ins. diam., bears N. 23° E., 21 lks. dist., mkd. T3S R34E S30 BT.

A fir, 22 ins. diam., bears N. 20° W., 118 lks. dist., mkd. T3S R33½E S25 BT.

Deposit corner stone alongside iron post.

UNION COUNTY
SURVEYOR

Date Received 3/15/12

Date Filed 3/15/13

By [Signature] DEPUTY

File No. 379-2013R

T3S34V01