


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

Index File No. X-21

**History of original corner establishment:**

Corner was originally established by Rufus S. Moore under GLO contract No. 451 during November, 1881. Surveyor's General's notes state: "set a post 3 ft, long 3 ins, in the ground for 1/4 sec. cor. marked 1/4S on W. face. From which: A pine 15 ins. diam, bears S47°W, 19 lks. dist. marked 1/4S BT. A pine 15 ins. diam, bears S39°E, 28 lks. dist. marked 1/4S BT."



**Description of corner evidence found:**

Found no trace of record post. Found a 24" pine with grown over blaze and old location tag. Measured N47°W, 14.0 ft. and at S39°E, 18.0 ft. found 12" stump, rotten pine.

**Description of monument and accessories established to perpetuate the original location of this corner:**

At above point set 2 1/2" X 30" galvanized pipe and brass cap marked; Set pipe 22" in the ground and mound of stone around to cap.

From which by magnetic declination of N20°E; A 26" pine bears S61°E, 139.7 ft. scribed 1/4S36 BT. Painted blazes red and 6" red band around. Placed 54↔3, 54↔4 and brass washers stamped PLS 1051 on BTs. Old BTs are signed. Placed 54↔2 and 54↔4 on steel fence post 5' north of the corner.

T3S R34E  
1/4  
S35 † S36  
OR PLS 1051  
1980

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland  
Doug Moser

October 21, 1980

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Barry B. Barbour*  
OREGON  
OCT. 17, 1975  
BARRY B. BARBOUR  
1051

Office of... B. B. Barbour ..... County of... Union .....  
State of... Oregon ..... I hereby certify that the within instrument was filed in this office  
for record on the... 30th day of... January ..... , 1981  
..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_  
 ☆ GPO-798-276  
 Date Filed \_\_\_\_\_  
 By \_\_\_\_\_  
 File No. 398-84 R