

18-70A

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

(T3S R34E) <sup>21</sup>

Z-23

History of original corner establishment:

Corner established by General Land Office contract survey


The original notes state:

West on South boundary of Section 36.

40.00 Set post 4 ft. long 3 in. square, 24" in ground for  $\frac{1}{4}$  section corner marked  $\frac{1}{4}$  South on North face from which:

Pine 40" dia bears S17°E 35 lks dist marked  $\frac{1}{4}$  SBT

Pine 9" dia bears N3°E 36 lks dist marked  $\frac{1}{4}$  SBT



Description of corner evidence found:

Found 20" stump with scribe S17°E at a distance of 23.4 ft.

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 30" galvanized pipe with an eight inch plate welded to bottom and a bronze cap on top. The hole was back filled with stone and tamped soil.

I stamped the disk.

From the monument the original bearing trees were; (none), I established the following new bearing trees; Yellow Pine 12" dia N13°W at a distance of 29 ft. and scribed  $\frac{1}{4}$  S BT; Yellow Pine 6" dia S25°E at a distance of 15.5 ft. and scribed  $\frac{1}{4}$  S BT;

The distance measured to center of respective trees on level. I placed bearing tree signs on both old and new bearing trees and painted stripes around trees. I placed a steel fence post with USFS sign 54-4 attached near corner and indicating USFS land to southwest and private land to the north.

$\frac{1}{4}$  COR  
T3S T4S  
R34E

S 36

S1

GRE LIC 381  
1970

Office of ..... County Surveyor ..... County of Union

State of Oregon, I hereby certify that the within instrument was filed in this office

for record on the 4th day of August, 1970, at 4 o'clock P.m., (signed)

County Surveyor  
(COUNTY OFFICIAL)

by

*James E. [Signature]*  
(REVEY)

UNION COUNTY SURVEYOR

Date Received 6-22-84

Date Filed 6-22-84

By G. LANGLITZ, DEPUTY

File No. 867-84R