


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. G-75 ¹

History of original corner establishment:

Corner was originally established by Rufus S. Moore under GLO contract No. 451 during November, 1882. Surveyor General's notes state: "Set post 3 1/2 ft. long, 3 ins. square, 18 ins. in the ground (with a mound of stone 3 ft. at the base, 18 ins. high on an open ridge). marked 1/4S on the E and W faces. A pine 20 ins. diam. bears N24°W, 123 lks. dist. marked 1/4S BT."



Description of corner evidence found:

Found no trace of record post. Falls in road. Found down 16" pine, scribed "1/4S B". Measured S24°E, 81.2 ft.


Corner falls on west edge of road.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2 1/2" X 30" galvanized pipe and brass cap marked:
Set pipe 15" in the ground and mound of stone around to cap.

From which by magnetic declination of N20°E:

A 16" poine bears S54°E, 106.2 ft. scribed 1/4S7 BT. A 12" pine bears S62°W, 11.2 ft. scribed 1/4S12 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-4s and brass washers stamped PLS 1051 on BTs. Palced 54-2 and 54-4 on steel fence post 5' south of the corner.



I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland
Steve Campbell

September 18, 1980

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

**OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051**

Office of.....County Surveyor..... County of..... Union.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..30th day of...January....., 1981..

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR	
Date Received	_____
Date Filed	_____ <small>★ PPO-798-276</small>
By	_____
File No.	<u>386-84 R</u>