


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

CORNER NOT SET IN ORIGINAL SURVEY by Rufus S. Moore in 1882.



Description of corner evidence found:

Description of monument and accessories established to perpetuate the original location of this corner: I set a 2 1/2" x 30" galvanized iron pipe with a brass cap 18" in the ground and built a mound of stone, at the corner position, from which BTs.


A fir 9 inches in diameter bears N 66 W a distance of 9.7 feet, marked 1/16 S. 16 BT.

A pine 10" in diameter bears S 53 E a distance of 97.5 feet, marked 1/16 S 15 BT.

I placed a nail and a brass washer marked O.P.L.S. 991 at the BT. blaze.

I used a steel tape and a magnetic compass with 20 degrees East declination set into the compass.

I set a steel post with a sign 5.0 feet south of the corner.



REGISTERED PROFESSIONAL LAND SURVEYOR

Gregory T. Blackman

OREGON
JUL 3, 1978
GREGORY T. BLACKMAN
991

Office of Surveyor County of Union
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 18 day of Sept 1978
J. Vaels by S. Miller
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed _____

By _____

File No. 419-84 R