History of original corner establishments

Original survey by General Land Office contract survey 1883 The original survey states; Set a basalt stone 18x18x12 inns. for corner to section 16,17,20and21 from which; A fir 12" in diam bears N61°E 24 lks dist marked T3S R35E S16BT. A tamarack 40" in diam bears N47°W 40 lks dist marked T3S R35E S17 BT; A fir 35" in diam bears S60°W 40 lks dist marked T3S R35E S20 BT.; A fir 5" in diam bears S48°E 25 lks dist marked T3S R35E S21

-	N-9
	DIAGRAM
	T3S R35EWM S17 S16 S20 S21
bσ	

Found - A fir 15" in diam bears N61°E 24 lks dist with scribe and in good condition. Found - A fir 10" in diam bears S48°E 25 lks dist with scribe and in good condition. Found - A down tamarack 40" in diam bears N#5°W 40 lks dist with scribe visible.



riginal location of this ex

At the postion of the corner I set a 2" galvanized pine 30 ins long and with a 8" plate welded to bottom and a bronze cap on top.

I stamped the disk

COR T3S R35E S20 S21 ORE LITC 381 1969

From the pipe monument the original bearing trees are; A fir 15 " in diam bears N61°E 24 lks dist. A fir 10" in diam bears S48°E 25 lks dist. I established two new bearing trees; A fir ll" in diam bears N65°W 17.3 ft. dist marked T3S R35E S17BT.; A fir l3" in diam bears S20°W 74 ft. dist marked T3S R35E S20BT. (distance measured to center of respective trees and marked with scribe) I set a steel fence post with USFS sign 54-4 attached. I placed bearing tree signs on both old and new bearing trees shoulder high facing the corner.

The state of the s	(elgned)
,	ate Received
Da	ate Filed
Ву	