CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1882 by Rufus S. Moore under General Land Office contract no. 451.

SURVEYORS GENERAL RECORD STATES

Set post for $\frac{1}{4}$ cor.

From which:

A fir 16" in dia. bears S 60 E, 83 lks. A fir 22" in dia. bears N 13 W, 38 lks.

DIAGRAM							
T	3\$		R	35	E		
	1 -	s	14				
	4	S	23				


Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner: I set a $2\frac{1}{2}$ "x30" galvanized iron pipe with a brass cap 10" in the ground in a rock outcrop, and raised a large mound of stone at the proportionate distance between the NW corner of section 23 and the NE corner of section 23 from which New BTS.

A fir 20" in diameter bears S 24 W a distance of 68.5 feet, marked $\frac{1}{4}$ S 23 BT.

A fir 11" in diameter bears N 22 E a distance of 90.00 feet, marked 2S 14 BT.



I placed a nail and a brass washer marked O.F.L.S 991 at the BT. blaze.

I set a steel fence post 10 feet west of the corner, (rocky ground prevented us from placing corner the required 5.0 feet from the corner.)

I used a steel tape and a magnetic compass with 20 degrees East declination set into the compass.

	LAND SURVEYOR
	Gryon T. Backene
Office of Cres County of Ones. I hereby certify that the within instrument was filed in this or	OREGON JULY 13. 873 EREJORY T. BLACKMAN 991
Office of County	USION COUNTY SURVEYOR
R6-7100-57 (9/71)	Data Received

Form R

Date Filed

425-84 R

REGISTERED PROFESSIONAL