## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1882 by Rufus S. Moore under General Land Offoce contract no. 451.

SURVEYORS GENERAL RECORD STATES

Set basalt stone 12 x 12 x 5 for cor. to sects. 13-14-23-24, marked with 3 notches on S. and 1 notch on E. edges, raised mound of stone along side.

DIAGRAM T 3 S	R 35 E
S 14	S <sub>.</sub> 13
S 23	S 24

T 35

5 23

1978

PLS 991

R 35 E

5 13

5 24

No restoration appears in the county records.

## Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the

original location of this corner: I set a  $2\frac{1}{2}$ "x30" galvanized iron pipe with brass cap 20" in the ground by a double proportion measurement from the  $\frac{1}{4}$  section corner to the North being the  $W_4^1$  section corner of section 14, from the  $S_4^1$  section corner of Section 13, from the  $E_4^1$  section corner of Section 23, from the NW section corner of section 23, from which New BTS.

A pine 12" in diameter bears N 39 W a distance of 83.7 feet, marked T 3 S R 35 E S 14 BT.

A fir  $22^n$  in diameter bears S 12 E a distance of 30.0 feet, marked T 3 S R 35 E S 24 BT

A pine 22" in diameter bears S 29 W a distance of 27.3 feet, Marked T 3 S R 35 E S 23 BT

No tree available in the NE quadrant.

I placed a nail and a brass washer marked O.P.L.S. 991 at the BT. blaze.

I set a steel fence post 5.0 feet West of the corner.

I used a steel tape and a magnetic compass with 20 degrees East declination set into the compass. REGISTERED **PROFESSIONAL** AND SURVEYOR Legos Ti Blacken Surveyor County of Union BRESORY T. BLACKMAN 991 LULION COUNTY (COUNTY FICIAL) DEURVEYOR Form R6-7100-57 (9/71) ☆ GPO 799-509 Date Received Date Filed\_