

OREGON CORNER RESTORATION FORM

Section 36 Township 3S Range 35E

County Union Date 5-03-95

CORNER DESIGNATION: V-21

Previous Renewals/Surveys, etc. This corner was originally set by U.S. Deputy Surveyor R. Moore under contract No.451 dated June 12,1882. The Surveyor Generals notes state: Set a basalt stone 18"x 12"x 7" 18 ins. in ground for corner to secs. 25,26,35 & 36 marked with 1 notch on S. and 1 notch on E. edges. From which;

A pine 30 ins.diam. brs. N 60° W 36 lks.dist.

Monument(s) & Accessories Found: (Condition and Source) Found a 38" pine stump with visible axe marks, no scribes visible. No evidence of original stone was found.

Monument Detail:

PLS 2360

Monument Set (Procedures and Description): At position established from original bearing tree stump, set a 5/8"x 30" rebar 20" deep with a 1 1/2" aluminum cap stamped PLS 2360 attached and surrounded with a mound of stones.

New Accessories:

A 9" ponderosa pine bears N 85° W, 120.8 feet marked T 3 S R 35 E S26 BT.

A 15" ponderosa pine bears S 79°W 100.9 feet marked T 3 S R 35 E S 35 BT.

A PK nail driven into a rock bluff 2.5 feet above the ground bears N 59°W 34.1 feet.

A PK nail driven into a rock bluff 2.0 feet above the ground bears N 39° W 11.1 feet.

Location & Comments:Corner is located 11 feet south of a rock bluff and 40 feet North of the north edge of Meadow creek.


Compass Declination: 18° E

Firm/agency: Tomkins-wells Joint Venture
Land Surveying
P.O. Box 1696
Pendleton, Oregon 97801

Surveyor's Seal



Paul W. P. Tomkins



Renews 6/30/96
5/07/95

Party Chief: Greg Flowers
Notes: Greg Flowers
Witness: Todd Rosenbalm

UNION COUNTY SURVEYOR
Date Received 5/9/95
Date Filed 5/11/95
By [Signature]
File No. 064-1995R