CERTIFIED RECORD OF LAND CORNER MONUMENTATION

A-1

Index File No. 7-25

History of original corner establishment:

In 1874, under GLO Contract No. 201, J. Hurlburt set post 5 ft. long 5 ins. square marked T2S S31 on NE., R36E S6 on SE, T3S S1 on SW and R35E S36 on NW Faces. A Fir 15 ins. diam. bears N78°E, 19 lks. dist., marked T2S R36E S31 BT. A Fir 24 ins. dia. bears N74°W 29 lks. dist., marked T2S, R35E S36 BT. A Fir 24 ins. dia. bears S30°W 20 lks. dist., marked T3S R35E S1 BT. A Pine 24" dia. bears S24°E, 36 lks. dist., marked T3S R36E S6 BT.

nucx	1116	NO.	
DIA	GRAM		
R35E	R	36E	
36	31	T29	3
1	6	T39	S

Description of corner evidence found:

Found 33" P.Pine alive with open upper blaze and visible scribing "R36 S6", lower blaze is healed over.
Found 12" dia. rotted Fir stump 5 ft. tall and leaning with visible scribing "T2S R36E S31" with chaining notch below and BT blaze has been burnt - no scribing visible.
Found rotted remains of stump at record bearings and distance for possible SW and NW BT's.

No evidence of original post.

Description of monument and accessories I established to perpetuate the original location of this corner:

At record bearing and dist. (N24°W, 23.76 ft) from S.E. found BT. Set $2\frac{1}{2}$ "x30" galvanized pipe with brass cap stamped:

Did not use NE stump because of the lean and not being able to determine the exact original location. Set pipe 23" in ground. No stones for mound.

T2S R35E | R36E S36 | S31 S1 | S6 T3S PLS 1099 1982

Bearing Trees:

Found stump in S31 T2S R36E, Bears N79°E 12.6 ft.

New BT's:

A Doug. Fir 10" dia. bears N42½°E, 12.7 feet, scribed T2S R36E S31 BT.

A Doug. Fir 11" dia. bears S58°W, 70.2 ft., scribed T3S R35E S1 BT.

A Doug. Fir 8" dia. bears N51°W, 22.9 ft., scribed T2S R35E S36 BT.

Painted blazes and attached signs as per $\frac{\text{Standard Specifications for Cadastral Surveys}}{\text{Most Set Set Metal post 5 ft. south of corner with 54-4 sign attached.}}$

Corner falls on slight SE slope approx. 150 ft. north of old seldom used logging road 0.5 miles SE of Road 2145 where it turns north.

Compass Declination: 18½° E

Witnesses: R. Orton

I hereby certify the above described corner monument and/or accessories was established as described on July 30, 1982.

LAND SURVEYOR
Land S. Sanglet
OREGON O
GARY L. LANGLITZ

COUNTY

REGISTERED

PROFESSIONAL

Office of Surveyor	County of Union	
Onogon	certify that the within instrument was filed in SER	
(COUNTY OFFICIAL)	DEPUT)	Data Bassimod

Form R6-7100-57 (9/71)

SURVETOR	_
Date Received	
☆ GPO 799-509 Date Filed	
Ву	
File No. 222-84 R	