CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: None. Corner established as part of this survey

DIAGRAM T3S R36E $C_{\frac{1}{4}}$. S1 1994 PLS 1106

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position established by survey: Set a $2\frac{1}{2}$ " X 30" aluminum pipe with a $2\frac{1}{2}$ " aluminum cap, buried 15" in ground. Monument is surrounded with a mound of earth and stone. Set a 6' steel fence post 4' N of monument with signs 54-9 & 54-3 attached.

New reference monuments established:

A 5/8"X30" rebar A 5/8"X30" rebar with a $1\frac{1}{2}$ " alum with a $1\frac{1}{2}$ " alum. cap bears $N33\frac{1}{2}$ °E-32.4'. Cap is stamped as shown:

cap bears S724°E-25.7'. Cap is stamped as shown: A 5/8"X30" rebar with a $1\frac{1}{2}$ " alum. cap bears S48°W-31.5'. Cap is stamped as shown: A 5/8"X30" rebar with a $1\frac{1}{2}$ " alum. cap bears N28°W 23.3'. Cap is stamped as shown

RM C4 S1 1 32.4' 1994 PLS 1106

RMC1 S1 * 25.7' 1994 PLS 1106

C4 S1 31.5' 1994 PLS 1106

RM

C1 S1 23.3' 1994 PLS 1106

All RM's have a 6'steel fence post with sign 54-9 & 54-3 attached.

A Warren Knight staff compass and steel tape was used to tie the reference monuments.

I hereby certify that the above corner monument was properly monumented to U.S.F.S. standards by me on November 11, 1994. Compass declination 18° East. REGISTERED

Witnessed by: Greg E. Flowers, LSIT and Todd Rosenbalm

PROFESSIONAL LAND SURVEYOR

Office of...... County of.....

State of......, I hereby certify that the within instrument was filed in this office Wall. R. well. for record on the...... day of......, 19.....

UNBOOT, COUNTY (COUNTY OFFICIAL)

OREGON JULY 22, 19// WILLIAM R. WELLS SURVEYOR 1106

Form R6-7100-57 (9/71)