


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

D-20

History of original corner establishment:
None. Corner was established as part of this survey.



Description of corner evidence found:

There is a North-South fence 1' West of corner and a fence corner, running South and East, located 75 feet North of corner.

Description of monument and accessories established to perpetuate the original location of this corner:

At position established by survey:

Set a 2 1/2" X 30" aluminum pipe with a 2 1/2" aluminum cap, buried 19" in ground and surrounded with a mound of earth and stone.
Attached signs 54-9 and 54-2 to 6' steel fence posts - 3' South and 3' East of monument.

New bearing trees established:

A 12" ponderosa pine bears N 17 1/2° E - 50.7 ft., scribed "SE 1/16 S2BT".
A 25" ponderosa pine bears S 61 3/4° E - 61.7 ft., scribed "SE 1/16 S2BT".
New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

Bearing trees were tied using a Sokkia Automatic Total Station.

I hereby certify that the above corner monument was properly monumented to U.S.F.S. standards by me on November 10, 1994.

Compass declination 18° East.

Witnessed by: Greg E. Flowers, LSIT
Todd Rosenbalm

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19..... *renews 6/30/96*

..... by
(COUNTY OFFICIAL)

UNION COUNTY
(DEPUTY) SURVEYOR
Date Received 7-10-96
Date Filed 7-10-96
By R. ROBINSON, DEPUTY
File No. 070-1996R

★ GPO-788-276