


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

D-23

History of original corner establishment:
None. Corner established as part of this survey.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At position established by survey:

Set a 2½" X 30" aluminum pipe with a 2½" aluminum cap, set 2" in the ground due to rimrock. Surrounded with a mound of earth and stone.

Set a 6' steel fence post 4' North of monument with sign 54-2 attached.

Set a 6' steel fence post 4' West of monument with signs 54-2 and 54-9 attached.

New corner accessories established:

A 5/8" x 30" rebar with a 1½" aluminum cap bears S 27½° E - 10.3', stamped as shown:

RM
CS 1/16 S1
↖
10.3 ft
1994
PLS 1106

A 19" ponderosa pine bears N 45 1/4° W - 149.8 ft., scribed "CS 1/16 S1 BT". New bearing tree has a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree. RM is surrounded with a rock mound and a steel fence post S.E. of RM with sign 54-9 attached.

Bearing tree and reference monument were tied using a Sokkia Automatic Total Station.

I hereby certify that the above corner monument was properly monumented to U.S.F.S. standards by me on November 11, 1994.

Compass declination 18° East.

Witnessed by: Greg E. Flowers, LSIT and Todd Rosenbalm

REGISTERED PROFESSIONAL LAND SURVEYOR

Will. R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL)

UNION COUNTY SURVEYOR
Date Received <u>7-10-96</u>
Date Filed <u>7-10-96</u>
By <u>R. ROBINSON, DEPUTY</u>
File No. <u>072-1996R</u>

rmwms 6/30/98

★ GPO—798-276