USDA-FOREST SERVICE GPO	940 117	and the second s
index		•
File No G-13	CORNER RECORD (SEARCH) Tract or Cor.	E. 1/4 C
T3S_R. 36 E	R.D. LATGRANDE County UNION Cor.	SEC. 9
Merid. WILLAMETTE	County UNION	
CORNER DIAGRAM	N.F. WALLOWA-WHITMAN State OREGON	
	DESCRIBE CORNER MONUMENT FOUND	
	Wood post gone, Small rock left where wood post should be.	
n / 90 /0		
.	DESCRIBE REARING TREES OF OTHER	_
1	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	
1	ponderosa pine, sec. 9. brs. N. 830 U 19 11-	
	22" ponderosa pine, sec. 10, brs. N. 18° E. 25 1ks.	
	6 25 1KS.	
PHOTO IDENTIFICATION DATA		
Photo No. EWD 34-32		
Filed At.		
Object Ident.		
ldent, By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH	3
Signature	<b>→</b> [	CORNER
PLANE COORDINATE POSITION DATA	4	
State Zone		
X Zone		
Y		
Estab. By		
Agency		
Signature	Title Division U	
LARRY MONICAL	Meddaugriers Deta	<del>4</del> 2·(3/68)
	6/9/7µ /100-5	4 (13/68)

UNION COUNTY SURVEYOR
Date Received
Date Filed 12-21-87
BY G. LANGLITZ, DEPUTY
File No. 254-87R