
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: This corner was never established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

See Map of Survey Number 028-1992.

## Description of monument and accessories I established to perpetuate the

original location of this corner: At position, determined by survey I set a 2½"x30" aluminum pipe with aluminum cap marked as shown, 30 inches in the ground, from which;

New Bearing Trees or Object; A 5/8"x30" rebar with a 2" aluminum cap bears S52°W, 5.99 feet marked T3S R36E RM E 1/16 S11 5.99 1992 OPLS 644. A 5/8"x30" rebar with a 2" aluminum cap bears N49°W, 7.65 feet marked T3S R36E RM E 1/16 S11 7.65 1992 OPLS 644.

Set a steel fence post approximately 5 feet North, with a 54-9 and a 54-2 sign attached.


I hereby certify that the above corner point was perpetuated as hereon described on August 4, 1992.

Witness: Jim Bennett

REGISTERED

DUANE I. GRIFFITH 644

Pete Crabtree Jeff Peterson



**PROFESSIONAL** LAND SURVEYOR OREGON

I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of	County of
State of , ! hereby	y certify that the within instrument was filed in this office
for record on the day of	······································
(COUNTY OFFICIAL)	(DEPUY)
Form R6-7100-57 (9/71)	Data Descived 1//23/92

File No.

\*GPO-591-971, 1988

2-2

6-20 5720