


Index _____ **CORNER RECORD (SEARCH)** Tract or _____ Cor. **S. 1/4 COR.**
 File No. J-3 (Ref. FSM 7151.4) Survey No. _____ No. **SEC. 7**
 T 3S R. 36 E R.D. LA GRANDE County UNION
 Merid. WILLAMETTE N.F. WALLOWA-WHITMAN State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Ponderosa pine stump, rotten with scribe visible in sec. 18.
 Douglas fir, stump rotten with scribe visible in sec. 7.
 B.T. in sec. 18 brs. N. 15° E. 30°.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Agency

Signature _____
 5/19/71

Title _____ Division _____ Headquarters _____ Date _____ 7100-52 (3.68)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed 12-21-87

By G. LANGLITZ, DEPUTY

File No. 255-87R

5-3