USDA-FOREST SERVICE GPO 9	40-117 N. 1/ Cam
Index File No. <u>J 23</u>	CORNER RECORD (SEARCH) Tract or Cor. No. 1/4 Cor. (Ref. FSM 7151.4) Survey No. No. Sec. 13
t <u>3S</u> R. <u>36E</u>	R.D. La Grande County Union
Merid. <u>Willamette</u>	N.F. W-W State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
12	Basalt stone 24 x 18 x 12 inches, 12 inches above the ground in good condition, 1/4 on the NE face, I don't believe the stone has been moved. It is located about 8' N. of a fence corner. N. x W. I posted only one tree here. The
13	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND fence runs directly West to the road.
PHOTO IDENTIFICATION DATA	
Photo No.	
Filed At.	
Object Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature	<u>7</u>
PLANE COORDINATE POSITION DATA	
State Zone	- -
Υ	
Estab. By	_ 8
Signature John Mitchel	Title Division Headquarters Date 7100-52-(3:68) 9/8/76

UNION	COUNTY
SUR	/EYOR

Date Received

Date Filed 12 -21-87

B)G, LANGZITZ, DEPUTY

File No. <u>258-87R</u>

J-23