
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner was never established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

See Map of Survey Number 028-1992.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position, determined by survey I set a 2½"x30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, from which;

New Bearing Trees; A 12 inch diameter Ponderosa Pine bears S9°W, 8.36 feet marked X BT A 18 inch diameter Ponderosa pine bears N21°W, 19.29 feet marked CN 1/16 S14 BT.

Set a steel fence post approximately 5 feet North, with a 54-9 and a 54-2 sign attached.

I hereby certify that the above corner point was perpetuated as hereon described on July 29, 1992.

Witness:

Jim Bennett Pete Crabtree Jeff Peterson



REGISTERED PROFESSIONAL AND SURVEYOR

OREGON JULY 10, 1964 DUANE I. GRIFFITH I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Form R6-7100-57 (9/71)

2...e

Data Faccived 11/23/92
Data Faccived 4/28/92
By Shy Black

*GPO-591-971, 1988

K-19 6019