


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

History of original corner establishment:  
This corner was never established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

See Map of Survey Number 028-1992.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position, determined by survey I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 30 inches in the ground, from which;


New Bearing Trees;

- A 5/8"x30" rebar bears N46°E, 5.80 feet marked T3S R36E RM C 1/4 S15 5.80 1992 OPLS 644
  - A 5/8"x30" rebar bears S48°E, 6.34 feet marked T3S R36E RM C 1/4 S15 6.34 1992 OPLS 644
  - A 5/8"x30" rebar bears S46°W, 5.57 feet marked T3S R36E RM C 1/4 S15 5.57 1992 OPLS 644
  - A 5/8"x30" rebar bears N48°W, 6.39 feet marked T3S R36E RM C 1/4 S15 6.39 1992 OPLS 644
- Raised small mound of stone, 3 foot base to top of cap.

Set a steel fence post approximately 5 feet North, with a 54-9 & 54-4 signs attached.

I hereby certify that the above corner point was perpetuated as hereon described on September 1, 1992.

Witness: Jim Bennett  
Jeff Peterson



**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

OREGON  
JULY 10, 1964  
**DUANE I. GRIFFITH**  
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of.....  
.....  
(COUNTY OFFICIAL) BY..... (DEPUTY)

**UNION COUNTY  
SURVEYOR**

Date Received 11/23/92

Date Filed 11/28/92

By [Signature]

File No. 126-1992R

Form R6-7100-57 (9/71)

\*GPO-591-971, 1988