## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1873 by J. Hurlburt under General Land Office contract No. 201. Surveyor General's records state:

Set basalt stone 20 x 12 x 8 - 8 in. in ground and made stone mound 2 ft. high for 1/4 Sec. Cor.

Index File No. N-7
DIAGRAM
T3S R36E
1/4

Description of corner evidence found:

Could find no evidence of the original stone.

Description of monument and accessories I established to perpetuate the original location of this corner: At a point established by single proportion measurements set  $2\frac{1}{2}$ "x30" galvanized pipe with brass cap stamped:

Set pipe 11" in ground with mound of stone to cap.

From which:

A P. Pine 8" in dia. bears N47°E, 132.9 ft., scribed 1/4 S17 BT. A P. Pine 12" in dia. bears  $S18^{\circ}E$ , 244.8 ft., scribed 1/4 S20 BT. Attached 54-3 signs to both BTs. Attached brass washers stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs red. Attached 54-2 and 54-4 signs to metal fence post 5' South of corner. Attached 54-2 sign to metal fence post 5' East of corner.

**T3S** R36E WM S17 **S20** 1979 OR PLS 1294

I hereby certify the above corner monument was reestablished as herein described on November 27, 1979.

Witnesses: G. Wagoner

D. Allen

REGISTERED **PROFESSIONAL** LAND SURVEYOR ulx OREGON
SEPTEMBER 23, 1977
HOWARD L. PERRY
1 2 9 4

File No. 436-84 R

Office of	he within instrument was filed in , 197.9	this office UNION COUNTY SURVEYOR
(COUNTY OFFICIAL)	(DEPUTY)	
Form R6-7100-57 (9/71)		Date Received_ ☆ aPO—798-276  Date Filed

## OREGON CORNER RESTORATION FORM

Section 20 Township 3S Range 36E

County Union Date 7-14-87

Corner Designation 27 16 X Condition Report Only Not Found Renewed Unrecorded Surveyed In Referenced Out

Previous Renewals/Surveys, etc.

1873 Hurlburt- 1979 Howard Perry (single Proportioned)

## Monument(s) & Accessories Found: (Condition and Source)

Found  $2\frac{1}{2}$ " Iron Pipe with Brasscap 12" above mound of stone Found 9" Ponderosa Pine N47°E-131.5' double blazed with scribes "%S17BT" visible.

Found 14" Ponderosa Pine S18°E-237.3' double blazed with scribes " $^{1}_{4}$ S20BT" visible.

Both BTs have corner tags. Found metal fence posts with Forest Service sign 9' south and 5' east of corner.

Found 1 Tron pipe 12" above a mound of stone bears N30°W-21.97'

Monument Detail

T35 R3CEWM

1/4 517
520
1979

OR PLS 1294

Fd. 1/2"I. Pipe

in mound of

Hone.

131.5

Fd. 21/2"I. Pipe with

N 30" W

21.97'

Fd. 14" Pond. Pine

Fd. 14" Pond. Pine

Monument Set (Procedures and Description)

REFER TO SURVEY 29-87

UNION COUNTY
SURVEYOR

Fig. Seceived 10-8-81

3, G. LAUGLITZ DEPU

138-87 R

Seal

## Location & Comments

New Accessories

Red Bridge State Park bearings & distances by hand compass & steel tape. Compass Declination

Firm/Agency Oregon State
Parks & Recreation Div.

Address

525 Trade Street SE Salem OR 97310

Party Chief R.Hill Notes R.Hill Witness H.Hanson REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 9, 1968 JOHN E HOLLINGSWORTH 691

 $\langle I. \rangle$ 

-