USDA-FOREST SERVICE GPO	940.117
File No P 21 T _3S R. 36E Merid Willamette	CORNER RECORD (SEARCH) Tract or Cor. W. 14 Cor. (Ref. FSM 7151.4) Survey No. No. Sec. 24
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
1 1 23 & 24	3' x 10' rock crib is near the corner point here at a fence corner S x W. Another fence corner bears about a chain west and the fence bears N x W at this corner. The corner stone could be in the large rock jack. The rock
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES
	of a large PP bear S. 48° E. about 220 lks The large rock jack could be out of position a few feet to the NW.
PHOTO IDENTIFICATION DATA	6
Photo No.	
Filed At.	
Object Ident.	
Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature	TO THE STATE OF THE REACH CORNER
PLANE COORDINATE POSITION DATA	
State Zone	1
X	
Estab. By	
Agency	
Signature	Title
John Mitchel	Title Division Headquarters Date 7100-52 (3/68)

1	UNION COUNTY SURVEYOR
	Date Received
	Date Filed 12-21-87
	BYS. LANGLITZ DEPUTY
	File No. 264-87R