


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

09

Index File No. Q-4

History of original corner establishment:

None Set



Description of corner evidence found:

Description of monument and accessories established to perpetuate the original location of this corner: At surveyed point set 2½"x30" galvanized pipe with brass cap stamped:
Set pipe 15" in ground to rock with mound of stone to cap.
From which:

T3S R36E WM
SE 1/16 | S19
1979
OR PLS 1294

A Douglas Fir 12" in dia. bears N27°W, 67.6 ft., scribed SE 1/16 S19BT.
A Douglas Fir 12" in dia. bears S46°E, 14.2 ft., scribed SE 1/16 S19BT.

Attached 54-3 signs to both BT's. Attached brass washers stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red. Attached 54-2 and 54-4 signs to metal fence post 5' South of corner. Attached 54-2 and 54-9 signs to metal fence post 5' East of corner.

I hereby certify the above corner monument was established as herein described.
November 20, 1979

Witnesses: G. Wagoner
D. Allen

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
SEPTEMBER 23, 1877
HOWARD L. PERRY
1294

Office of... County Surveyor..... County of... Union.....

State of... Oregon....., I hereby certify that the within instrument was filed in this office

for record on the..... day of....., 19... 79

..... by.....
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR

Date Received _____
GPO 799 509
Date Filed _____
By _____
File No. 443-84 R