History of original corner establishment: Corner established in 1873 by J. Hurlburt, under

General Land Office Contract No. 201. Surveyor General's records state:

Set basalt stone 20 x 10 x 3 - 10 in. in ground for 1/4 Sec. Cor.

•	Index File No. R-3		
	DIAGRAM		
	T3S R36E		
	1/4 S19 S30		

-11

Description of corner evidence found:

No evidence could be found of the original corner stone.

Description of monument and accessories I established to perpetuate the original location of this corner: At a point established by single proportion measurement set $2\frac{1}{2}$ "x30" galvanized T3S R36E WM **S19** pipe with brass cap stamped: 1/4 Set pipe 18" in ground to rock with mound of stone to cap. S30 From which: 1979 A P. Pine 12" in dia. bears N44°W, 135.0 ft., scribed 1/4 S19 BT. A stone 10'x7'x3½' high bears S26°E, 60.55 ft., etched B.O. "X". Attached 54-3 sign to BT. Painted blazes and 6" band around BT red. OR PLS 1294 Attached brass washer stamped LS 1294 to foot blaze of BT. Painted scribing on Bearing Object red. Attached 54-4 sign to metal fence post 5' East of corner.

> I hereby certify the above corner monument was reestablished as herein described on November 13, 1979.

> > Witnesses: G. Wagoner

D. Allen

M. Wagoner

G. Lester

REGISTERED **PROFESSIONAL** AND SURVEYOR OREGON SEPTEMBER 23. 1977 HOWARD L. PERRY

Office of County Surveyor County State of Oregon I hereby certify that the	unty ofUnion the within instrument was filed i	n this of other
ror record on the day of by	, 19./.9.	UNION COUNTY SURVEYOR
(COUNTY OFFICIAL)	(DEPUTY)	
orm R6-7100-57 (9/71)		Date Received
		Date Filed
		Ву
		File No. 446-84R