


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


None set.

Index File No. T-3



Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner: Surveyed point falls on very steep slope with solid rock 2" below surface; therefore unable to set monument. In a rock outcropping to the east set a brass tablet 3" in dia. with a 5/8"x3" stem 7.38 ft. East of the corner position stamped:



Bearing Trees to corner position.

A P. Pine 15" in dia. bears N65°E, 36.6 ft., scribed C1/4 S30 BT.

A P. Pine 18" in dia. bears S57°W, 116.4 ft., scribed C1/4 S30 BT.

Attached 54-3 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs red. Attached 54-2, 54-4 and 54-9 signs to metal fence post 6 ft. west of corner.

I hereby certify the above corner monument was established as herein described on November 28, 1979.

Witnesses: G. Wagoner
M. Wagoner
G. Lester

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

[Signature]
OREGON
SEPTEMBER 23, 1977
HOWARD L. PERRY
1294

Office of..... County Surveyor..... County of..... Union.....
State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 1979.
..... by

(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY
SURVEYOR**
Date Received _____
★ GPO—798-276
Date Filed _____
By _____
File No. 454-84 R