CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None Set.

<u>Index File No. T-4</u> DIAGRAM T3S R36E E 1/16 ---C

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner: At surveyed point set $2\frac{1}{2}$ "x30" galvanized pipe with brass cap stamped: Set brass cap 6" below surface with can over brass cap to protect it because corner falls in North shoulder of State Highway #244. From which:

T3S R36E WM E 1/16 \$30 1979 OR PLS 1294

A Douglas Fir 14" in dia. bears N57°W, 72.3 ft., scribed CE 1/16 S30BT.

A P. Pine 26" in dia. bears N58°E, 89.0 ft., scribed CE 1/16 S30BT. Attached 54-3 signs to both BT's. Attached brass washer stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red. Attached 54-2 and 54-4 signs to wood fence post 10' West of corner. Attached 54-2 and 54-9 signs to metal fence post 5' North of corner.

I hereby certify the above corner monument was established as herein described. November 19, 1979

Witnesses:

G. Wagoner D. Allen

REGISTERED PROFESSIONAL LAND SURVEYOR OREGON SEPTEMBER 23, 1977 HOWARD L. PERRY 1 2 9 4

State of Oregon, I hereby certify that the for record on the day of by	. <i>, 19</i> 79	UNION COUNTY SURVEYOR
(COUNTY OFFICIAL)	(DEPUTY)	
rm R6-7100-57 (9/71)		Date Received # GPO 799-509 Date Filed
		By