

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX FILE No. T-5


History of original corner establishment: Corner established in 1873 by J. Hurlburt, under General Land Office Contract No. 201.

Surveyor General's records state:

Set Pine post -4-ft. long 3 in. thick 2 ft. in ground for 1/4 Sec. Cor.

Pine 12 ins. dia. N72°W, 37 lks.

Pine 15 ins. dia. S39°E, 110 lks.



Description of corner evidence found:


At assumed corner location could find no trace of original corner post. Found 18 inch P. Pine, bearing S39°E, 110 lks. with Visible scribing in open blaze. Found 25 inch P. Pine bearing N72°W, 37 lks. with healed blaze.

Description of monument and accessories I established to perpetuate the

original location of this corner: Used recorded distances from faces of both found BT's to reestablish the original corner position, at which point set 2½"x30" galvanized pipe with brass cap stamped:

Set pipe 22" in the ground with mound of stone to cap.

T3S R36E WM



USE THE ORIGINAL BEARING TREES:

A P. Pine 18 inches in dia. bears S45°E, 72.6 feet with visible scribing in open blaze. (Dying)

A P. Pine 25 inches in dia. bears N64°W, 24.45 feet with healed blaze. Replaces Southeast dying BT.

P. Pine 15" in dia. bears N51°E, 102.2 ft. scribed 1/4 S29 BT.

Attached 54-3 and 54-4 signs to both BT's. Painted blazes and 6" band around both BT's orange. Attached 54-4 sign to metal fence post 5 ft. North of corner.

I hereby certify the above corner monument was reestablished as herein described on October 3, 1979.

Witnesses: R. Orton
M. Wagoner

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
SEPTEMBER 23, 1977
HOWARD L. PERRY
1294

Office of..... County Surveyor..... County of..... Union.....
State of..... Oregon..... I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 1979.

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____ ☆ GPO-798-276

Date Filed _____

By _____

File No. 456-84 R