
CERTIFIED RECORD OF LAND CORNER MONUMENT TION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established

DESCRIPTION OF CORNER EVIDENCE FOUND:

None



See Union County Survey Number 003-2009

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8" iron pin with aluminum cap marked as shown, 29 inches in the ground from which;

NEW BEARING TREES:

A 7" Ponderosa Pine bears South 27° East, a distance of 5.00 feet, marked X BT.

An 10" Ponderosa Pine bears South 53° West, a distance of 73.20 feet, marked E 1/16 S34 BT.


I set a steel fencepost 1 ft. North of corner position. An East/West running fenceline falls about 20' to the South and a North/South running fenceline falls approximately 250' to the West.

I hereby certify that the corner was set January 22, 2009 Witnesses: Greg T. Blackman Jr. & Jeff Hsu

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date: December 31, 2010



UNION COUNTY
SURVEYOR

Date Received 1/23/09

Date Filed By Ry T. Blow

File Number <u>OOI-COOYR</u>

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing tree. I attached a brass washer marked OPLS 2219 to the BT blaze.